Work Task: 26049 - 1



Monthly AST (Above-ground Storage Tank) Visual Inspection - Fluid Vessals

Description:

Monthly AST (Above-ground Storage Tank) Visual Inspection

Visually Inspect the outside of the container for (From SPCC Requirement [40 CFR 112.8(c)(6)]:

- Signs of deterioration
 Signs of Discharges
- 3. Signs of Accumulation of oil inside diked areas

Record finding in Work Order Close Out Comments.

Inspect all vessels on the attached list.

Work Type:

4. Environmental

Work order:

26049 Monthly AST (Above-ground Storage Tank) Visual Inspection

Entity to Work On

Number:

710

Name:

Common Plant Services

Personnel

Planner:

MacVeigh Craig

Supervisor:

Parker Sid

Shutdown Information

Shut entity down while work is in progress?

No

Seattle Plant

Printed by:

Austell Carey

Printed on:

5/3/2005

Page: 1 of 4

Other Entities to Shut Down						
Number	Name					
Time Frame for Completing th	e Work					
Priority:	3 Routine					
Start no earlier than:	2004/12/30 10:37:26.00					
Finish no later than:	2005/01/20 10:37:26.00					
Shutdown period:						
Estimated duration:						
Planned duration:	4.00 hours					
Job Premiums						
Job type:	·					
Shift:						
Backlog information:		,				
Probability of Satisfaction:	High					

Seattle Plant

Material availability:

Printed by:

Austell Carey

Material not required

Printed on:

5/3/2005

Estimated material availability date:

Failure Information						· · · · · · · · · · · · · · · · · · ·	
Consumts follows and bais information:	No						
Generate failure analysis information:	INO						
Reason for failure:							
Root cause:							
Action taken:							
Equipment failed due to:							
Entity:							
Catalog item:							
Requirements							
Part/Service		Quantity I	em Number	Probability of Satisfaction	Availability	Estimated Material Availability Date	Storeroom
Trade	Quantity	Time Requi	red				
PM Lube Spec	1.00	4.00 hours					

0.00 0.00 hour

Seattle Plant

PM Electrician

Printed by:

Austell Carey

Printed on:

5/3/2005

Safety Instructions for this Work

Work Task: Monthly AS	Γ (Above-ground Storage	Tank) Visual	Inspection	- Fluid '	Vessals
-----------------------	-------------------------	--------------	------------	-----------	---------

Activities							0731	
Activity Number	Activity		Record Statistics	Record Downtime	Component Movement	Calibration Instrument Used	Comments	GC2E000
								~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
Processe	d:	Processed on:		Done	by:			

Seattle Plant

Printed by:

Austell Carey

Printed on:

5/3/2005

Page: 4 of 4